

What Happened?

- Vibration caused failure
- Age and fatigued metals caused failure

Technician Solutions

- Replace Thermal Expansion Valve
- Possible System Replacement

Most newer air conditioning and heat pump systems have a TXV instead of a fixed orifice which meters the refrigerant flowing through the tubing. In addition to improper metering, the devices can also cause leaking.

