

What Happened?

- Rust
- Incorrect refrigerant charge
- Age

Technician Solutions

- Replace Accumulator
- Possible System Replacement

Accumulator's trap oil maintains clean refrigerant. Depending on the age of a unit it more be economical to replace. Maintenance agreements may have prevented this failure.

