

# Condenser Fan Blade

1

## What Happened?

- Age of Part
- Bent or Warped Blade
- Damaged rain and leaf guard
- Damage from vibration

## Technician Solutions

- Replace fan blade
- Maintenance agreement for proactive repair
- Possible unit replacement

A bent fan blade can be detected by a variation in the noise coming from the condensing unit. The system will not operate efficiently and may lose all capacity whatsoever. A maintenance agreement could prevent complete failure

