

What Happened?

- Deterioration due to age
- Soldered joints are deteriorated
- Sprinkler, animal and other damage from elements

Technician Solutions

- Replace coil
- Repair coil
- Replacing system may cost less than repairing

Most outdoor coils are made of copper yet there are some aluminum and are aluminum in parts. They become worn with time and are prone to leaks. If the coil is out of warranty, it is often less expensive to replace the unit. Condenser coils are expensive and time consuming to install.

